

## BANGALORE DIVISION.

*The 22nd March 1903.*

Notice is hereby given that sealed tenders will be received at the office of the Executive Engineer, Bangalore Division, up to 6th April 1903, for restoring Hoskur tank, Registered No. 201 of Anekal Taluk. An approximate estimate of quantities is given below. These quantities are not guaranteed. The work should be completed by the end of May 1904.

2. The plans, detailed estimate and conditions may be seen at the Executive Engineer's office at Bangalore between the hours of 11 A. M. and 5 P. M.

3. Tenders should be submitted on printed forms which may be obtained from the Executive Engineer. The tenders should be accompanied by a statement in the form given below showing the rates at which the different items specified will be executed.

4. Each tender must be accompanied by a deposit of Rs. 200 in cash or Government Promissory Notes, as earnest money, and be superscribed "Tender for restoring Hoskur tank, Registered No. 201 of Anekal," in default of which, tenders will be rejected.

5. The final acceptance of any tender will rest with the Chief Engineer, who does not bind himself to accept the lowest or any tender or to assign any reason whatever for the rejection of any tender.

6. Within eight days of the acceptance of the tender, the successful competitor will be required to execute the usual contract bond; in default of which, his tender will be considered cancelled, and his earnest money will be forfeited.

7. The name of the successful competitor, whose tender has been accepted, will be posted on the notice board in the Executive Engineer's office in due course. No enquiries regarding the acceptance or rejection of a tender will receive any reply.

8. On acceptance of one of the tenders, the earnest money on rejected tenders will be returned.

| Items of work.                               |              | Per          | Quantity or Rate. |
|--|--------------|--------------|-------------------|
|  | <i>Bund.</i> |              |                   |
| Earthwork                                    |              | C. yds.      | 8,367             |
| Old stone work                               |              | Do           | 937.18            |
| New stone work                               |              | Do           | 24.17             |
| Turfing                                      |              | S. yds.      | 4,736             |
| New grade stones                             |              | Each         | 28                |
| Registered number stones                     |              | "            | 1                 |
| B. M. stones                                 |              | "            | 2                 |
| Gauge stones                                 |              | "            | 1                 |
| Index stones.                                |              | "            | 56                |
| <i>Waste weir (195) extension.</i>           |              |              |                   |
| Dismantling masonry                          |              | C. ft.       | 1105              |
| Earthwork, excavation and draught below weir |              | C. yds.      | 4,603             |
| Clearing approaches above weir               |              | "            | 7,938             |
| Concrete in surki mortar                     |              | C. ft.       | 1,677             |
| Burnt brick in surki mortar                  |              | "            | 2,294             |
| Burnt stone slabs nicely dressed             |              | S. ft.       | 360               |
| Do "roughly dressed                          |              | "            | 632               |
| Plastering and pointing with surki mortar    |              | L. S. Rupees |                   |
| Rough stone work, new                        |              | C. yds.      | 713               |
| Old stone work                               |              | "            | 332               |
| Compensation for land                        |              | L. S. Rupees |                   |
| <i>Sluice.</i>                               |              |              |                   |
| Repairing sluice                             |              | L. S. Rupees |                   |

B. VENKATACHAR, *Executive Engineer.*

## KOLAR DIVISION.

*The 20th March 1903.*

Notice is hereby given that sealed tenders will be received at the office of the Executive Engineer, Kolar Division, up to 15th April 1903 noon, for restoring the Chendanaadur Tank, Registered No. 189, Goribidnur Taluk. An approximate estimate of quantities is given below. These quantities are not guaranteed. The work should be completed by the end of June 1905.

2. The plans, detailed estimate, and conditions may be seen at the Executive Engineer's office at Kolar between the hours of 11 A.M. and 5 P.M.

3. Tenders should be submitted on printed forms which may be obtained from the Executive Engineer. The tenders should be accompanied by a statement in the form given below, showing the rates at which the different items specified will be executed. The rates tendered should include royalty on stones, limestone, etc., removed from Government lands.

4. Each tender must be accompanied by a deposit of Rupees 500 in Government Promissory Notes, as earnest money, and be superscribed "Tender for restoring the Chendanadur tank, Registered No. 189, Goribidnur Taluk," in default of which, tenders will be rejected.

5. The final acceptance of any tender will rest with the Superintending Engineer, who does not bind himself to accept the lowest or any tender or to assign any reason whatever for the rejection of any tender.

6. Within eight days of the acceptance of the tender, the successful competitor will be required to execute the usual contract bond; in default of which, his tender will be considered cancelled, and his earnest money will be forfeited.

7. The name of the successful competitor, whose tender has been accepted will be posted on the notice board in the Executive Engineer's office in due course. No enquiries regarding the acceptance or rejection of a tender will receive any reply.

8. On acceptance of one of the tenders, the earnest money on rejected tenders will be returned.

## ABSTRACT.

| Items of work.                      | Per      | Quantity. |
|-------------------------------------|----------|-----------|
| <i>Bund.</i>                        |          |           |
| Earthwork                           | C. yds.  | 62,663    |
| Turfing                             | S. yds.  | 25,462    |
| New stone work                      | C. yds.  | 10,390    |
| B. M. stones                        | Each     | 2         |
| Grade stones                        | Do       | 89        |
| Year stone                          | Do       | 1         |
| Tank No. stone                      | Do       | 1         |
| Gravel backing                      | C. yds.  | 2,856     |
| Gauge stone                         | Each     | 1         |
| <i>Waste Weir 200'.</i>             |          |           |
| Earthwork                           | C. yds.  | 336       |
| Burnt brick in surki                | C. ft.   | 4,060     |
| Stone slabs                         | S. ft.   | 1,891     |
| Stone in chunam                     | C. ft.   | 664       |
| Concrete                            | C. ft.   | 1,015     |
| Rough stone work                    | C. yds.  | 50        |
| <i>Sluices.</i>                     |          |           |
| Examining and reconstructing        | Lump sum |           |
| <i>Anikat 250' ft. long.</i>        |          |           |
| Excavating sand                     | Lump sum |           |
| Baling water                        | Do       |           |
| Excavation in hard soil             | C. yds.  | 974       |
| Do soft rock                        |          | 391       |
| Burnt brick in surki                | C. ft.   | 11,526    |
| Burnt stone slabs                   | S. ft.   | 3,245     |
| Concrete                            | C. ft.   | 7,183     |
| Cutting holes etc., for joggles     | Lump sum |           |
| Chunam plastering                   | Sqr.     | 30-00     |
| Rough stone apron                   | Lump sum |           |
| Shutters for scouring sluice        | Do       |           |
| Dry stone work                      | C. yds.  | 160       |
| Training bank including tamping     | Do       | 336       |
| <i>Head sluice near anikat.</i>     |          |           |
| Excavating foundation and refilling | Lump sum |           |
| Burnt brick in surki                | C. ft.   | 2,123     |
| Burnt stone slabs                   | S. ft.   | 470       |
| Chunam plastering                   | Sqr.     | 10-16     |
| Shutters with iron etc., complete   | Each     | 4         |
| Cutting grooves                     | Lump sum |           |

| Item of work.   | Channel. | Per.      | Quantity. |
|---|----------|-----------|-----------|
| Earthwork   | ...      | C. yds.   | 19,364    |
| Soft rock excavation  | ...      | Do        | 9,225     |
| Dry stone revetment   | ...      | Do        | 50        |
| Earthwork to feed Chendanadur tank                          | ...      | Do        | 4,107     |
| <i>Cattle bridges Nos. 1, 2 and 3.</i>                      |          |           |           |
| Excavating foundation and refilling                         | ...      | Lump sum. |           |
| Burnt brick in surki  | ...      | C. ft.    | 2,376     |
| Do stone slabs  | ...      | S. ft.    | 672       |
| Chunam plastering   | ...      | Sqr.      | 10,35     |
| Dry stone work  | ...      | C. yds.   | 51        |
| Concrete  | ...      | C. ft.    | 318       |
| Forming the road and gravelling                             | ...      | Lump sum. |           |
| <i>Head sluice in Idagur tank to feed Chendanadur tank.</i> |          |           |           |
| Earthwork   | ...      | C. yds.   | 792       |
| Burnt stone in chunam                                       | ...      | C. ft.    | 516       |
| Burnt brick in surki  | ...      | Do        | 2,409     |
| Stone slabs   | ...      | S. ft.    | 592       |
| Rough stone work  | ...      | C. yds.   | 111       |
| Shutters with rod, etc., complete                           | ...      | Each      | 3         |
| Cutting grooves   | ...      | Lump sum. |           |
| <i>Miscellaneous.</i>                                       |          |           |           |
| Mile stone  | ...      | Each      | 2         |
| Half-furlong bank grade stones                              | ...      | Do        | 27        |
| Bed grade stones  | ...      | Do        | 28        |

B. SUBBA RAO, *Executive Engineer.*

## MYSORE DIVISION.

*Notice, dated 15th March 1903.*

A sum of Rs. 152-12-2 is due to deceased Mansur Sab, contractor, for planting in the vicinity of the Reserve Police Lines at Mysore from this office. If his heir or heirs do not appear before the Executive Engineer, Mysore Division, within next three months to receive payment of the said sum with proper heir certificate, it will be forfeited to Government.

K. KRISHNAIENGAR, *Offg. Executive Engineer.*

## KADUR DIVISION.

*The 19th March 1903.*

1. Notice is hereby given that sealed tenders will be received at the office of the Executive Engineer, Kadur Division, up to 10th April 1903, for constructing a 2nd class travellers' bungalow at Birur, Kadur Taluk. An approximate estimate of quantities is given below. These quantities are not guaranteed. The work should be completed by the end of March 1904.

2. The plans, detailed estimate and conditions may be seen at the Executive Engineer's office at Chikmagalur between the hours of 11 A.M. and 5 P.M.

3. Tenders should be submitted on printed forms which may be obtained from the Executive Engineer. The tenders should be accompanied by a statement in the form given below, showing the rates at which the different items specified will be executed.

4. Each tender must be accompanied by a deposit of rupees two hundred, in cash or Government Promissory Notes, as earnest money, and be superscribed "Tender for constructing a travellers' bungalow at Birur," in default of which, tenders will be rejected.

5. The final acceptance of any tender will rest with the Superintending Engineer, who does not bind himself to accept the lowest or any tender or to assign any reason whatever for the rejection of any tender.

6. Within eight days of the acceptance of the tender, the successful competitor will be required to execute the usual contract bond; in default of which, his tender will be considered cancelled, and his earnest money will be forfeited.

7. The name of the successful competitor, whose tender has been accepted, will be posted on the notice board in the Executive Engineer's office in due course. No enquiries regarding the acceptance or rejection of a tender will receive any reply.

8. On acceptance of one of the tenders, the earnest money on rejected tenders will be returned.

Abstract of estimate for constructing a new 2nd class travellers' bungalow at Birūr, Kadur Taluk.

| Items of work.  | Per.      | Quantity. | Rate. | Cost. |
|---|-----------|-----------|-------|-------|
| Clearing the site and levelling the ground  | Lump sum. |           |       |       |
| Earthwork excavation  | C. yd.    | 304       |       |       |
| Concrete  | C. ft.    | 3,856     |       |       |
| Burnt stone in chunam with bond slabs   | "         | 5,311     |       |       |
| Burnt brick in chunam   | "         | 4,724     |       |       |
| Do in mud   | "         | 2,474     |       |       |
| Burnt stone slabs, 6" thick, dressed in faces   | S. ft.    | 1,073     |       |       |
| Do 4" do  | "         | 125       |       |       |
| Teakwood work including wood oiling   | C. ft.    | 306       |       |       |
| Honne wood work do and tarring to exposed portion.  | "         | 98.38     |       |       |
| Roofing with 1st class Mangalore tiles and teak reepers etc.  | Sqr.      | 36.92     |       |       |
| Terracing   | "         | 14.72     |       |       |
| Teakwood planking (ceiling $\frac{1}{2}$ " thick) including oiling                                      | S. ft.    | 10.70     |       |       |
| Ridge tiles set in mortar   | R. ft.    | 170       |       |       |
| Flooding with 6" concrete and plastering over it  | C. ft.    | 25        |       |       |
| Do with gravel and cowdung washing and plastering.  | C. yd.    | .9        |       |       |
| Do with tiles and 3" concrete and cement pointing (tiles manufactured in the school of Arts in Mysore). | Sqr.      | 20.88     |       |       |
| Do with burnt stone slabs over 3" concrete and cement pointing.   | S. ft.    | 309       |       |       |
| Chunam pointing   | Sqr.      | 9.18      |       |       |
| White-washing 2 coats   | "         | 90.14     |       |       |
| Color do  | "         | 35.53     |       |       |
| Cornice work, ordinary  | R. ft.    | 218       |       |       |
| Chunam plastering   | Sqr.      | 107.24    |       |       |
| Mud do  | "         | 18.13     |       |       |
| Mangalore ventilating tiles   | Each      | 2         |       |       |
| Teakwood finials, large   | Each      | 2         |       |       |
| Do small  | "         | 4         |       |       |
| Cut stone pillars for verandah  | "         | 18        |       |       |
| Teakwood eave boards, ornamental 1" thick with painting   | R. ft.    | 124       |       |       |
| Honnewood shelves in leaths   | Lump sum. |           |       |       |
| Teakwood double doors (panelled)  | No.       | 2         |       |       |
| Teakwood doors  | "         | 5         |       |       |
| Do  | "         | 6         |       |       |
| Do windows with inside glazed shutters with iron bars   | "         | 9         |       |       |
| Do ventilators swing glazed large   | "         | 22        |       |       |
| Do do small   | "         | 2         |       |       |
| Honnewood doors, battened   | "         | 1         |       |       |
| Do ventilators with swing glazed shutters   | "         | 6         |       |       |
| Do windows with iron bars and shutters  | "         | 1         |       |       |
| Do ventilators, ordinary swing shutters   | "         | 1         |       |       |
| Chocolate painting to doors and windows   | Sqr.      | 17.00     |       |       |
| Cement plastering $\frac{1}{2}$ " thick under the eave of Mangalore roof to a width of 3 feet.          | Sqr.      | 3.60      |       |       |
| Tarring to latrine walls inside 3" high   | "         | 6.00      |       |       |
| Bamboo poles for stalls   | No.       | 6         |       |       |
| Zinc sheets to valice of out houses   | No.       | 4         |       |       |
| Constructing a cistern in the bath room of Native kitchen.  | Lump sum. |           |       |       |
| Drawing-well  | Do        |           |       |       |
| Line fence and gates for the compound   | Do        |           |       |       |
| Drainage pipes  | R. ft.    | 182       |       |       |
| Drilling holes in upright slabs for stalls  | No.       | 8         |       |       |

V. ARUNACHELLAM, Executive Engineer.

#### CHITALDRUG DIVISION.

Abstract Notification, dated 4th March 1903.

Repairing the Nagasamudra Tank, Register No. 114 of Molakalmuru Taluk.

Attention is invited to tenders called for the above work in the Mysore Gazette, dated 12th March 1903.

Y. SRINIVASA RAO, Executive Engineer.